


Concentration Diagram

Types of Damage

H = Hole

S = Smear

W = Wrinkle



This shipping box has several types of damage which can occur during packing and shipping. The relative location of each type of damage is shown on one diagram which represents many boxes. Note the large number of holes in the one location – this would lead the team to believe that some systematic cause is poking holes in the boxes and needs to be investigated.